

Why Gamble When Rebuilding a Honda or Acura Unit?

Go with a SURE BET!!!

STL-H04-295

Now Available!

- Lockup codes & clutch burnout
- Lockup clutch drag in gear
- Long, delayed, double bump reverse to drive engage when hot
- 1-2 slide bump
- Light to mid throttle 1-2 shudder
- Erratic weak shifts Converter/case bearing "walk"



STL-H04-323

- Lockup codes & clutch burnout
- Lockup clutch drag in gear
- Long, delayed, double bump reverse to drive engage when hot
- 1-2 slide bump
- Light to mid throttle 1-2 shudder
- Erratic weak shifts Converter/case bearing "walk"



STL-H04-365

- Lockup codes & clutch burnout
- T.C.C slip/shudder at low rpm in 3RD gear below 36 mph
- Long, delayed, or double bump reverse to drive engage when hot
- 1-2 slide bump
- Converter/case bearing "walk"
- Light to mid throttle 1-2 shudder



STL-H04-388

- Lockup codes & clutch burnout
- T.C.C slip/shudder at low rpm in 3RD gear below 36 mph
- Long, delayed, or double bump reverse to drive engage when hot
- 1-2 slide bump
- Erratic, slip, or bump shifts
- Light to mid throttle 1-2 shudder



STL-H05-388

- Lockup codes & clutch burnout
- T.C.C slip/shudder at low rpm in 3RD gear below 36 mph
- Long, delayed, or double bump reverse to drive engage when hot
- 1-2 slide bump
- Light to mid throttle 1-2 shudder
- Erratic, slip, or bump shifts



STL-H05-MDKA

- Lockup codes, clutch burnout, T.C.C slip/shudder at low rpm
- Lockup clutch drag in gear @ idle
- Light to mid throttle 1-2 shudder
- Double bump reverse to drive engage when hot
- 1-2 slide bump
- Erratic, slip, or bump shifts



STL-H05-4CYL

- Lockup codes & clutch burnout
- Lockup clutch drag in gear @ idle
- Long, delayed bump reverse to drive engage when hot
- Converter/case bearing "walk"
- Increased cooler flow/improved lube system



SUPERIOR SURE-COOL® KIT VEHICLE APPLICATION REFERENCE CHART:

Translab/Superior Part#	Box/Unit Codes
STL-H04-295	M4TA, MDLA, MDMA, MRVA, MCVA
STL-H04-323	A4RA, B4RA, M4RA, S4RA, BDRA, BMXA, SLXA, B46A
STL-H04-365	BAXA, B6VA, MAXA, MDWA, MPJA, M6HA
STL-H04-388	B7TA, B7VA, B7XA, B7YA, B7ZA, M7VA, M7ZA
STL-H05-388	BAYA, BGFA, BGHA, BGRA, BYBA, B7WA, MAYA, MGFA, MGHA, MGSA, M7WA (BDGA, BVGA, PVGA — *SEE NOTE)
STL-H05-MDKA	BDHA, BDKA, BJFA, BVLA, BWEA, BYFA, B36A, MDKA, MDPA, MDRA, MJBA, MJFA, MYFA, PN3A, PN4A, PSFA, PVLA, P34A, P35A, P36A, MURA-HYBRID (BDGA, BVGA, PVGA — *SEE NOTE)
STL-H05-4CYL	BCLA, BZHA, BZJA, BZKA-1, BZKA-5, BZKA-6, BZKA-7, BZNA-1, B90A, GPLA, GPAA-3, GPAA-4, MCLA, MCTA, MCVA, MKYA, MM2A, MM7A, MNZA-5, MP5A, MP5A, MRMA, MRVA, MZHA, MZJA, MZKA-1, MZKA-2, MZKA-3, MZKA-4, MZKA-5, MZKA-8, M91A, SMMA, SPCA, SP5A

Newly Updated Codes

*NOTE: 03-05 BVGA/PVGA Large Case use the STL-H05-388 kit • 06-up Pilot BVGA/PVGA 3.5 LL V-6 (large case w/ large gears) use STL-H05-MDKA kit • 04-06 BDGA use STL-H05-388 kit • 07-08 BDGA use STL-H05-MDKA kit • Address Questions at (850) 575-7155 or email: info@superiortransmission.com



PART# BB100

DON'T FORGET TO ORDER YOUR BENCH BUDDY®



PART# AB100

SUPERIOR TRANSMISSION PARTS, INC.

THE SIMPLE SOLUTION



www.superiortransmission.com

Connect with Superior Transmission Parts on Facebook & Twitter:

 Superior Transmission Parts, Inc.
  superiortrans1

Phone: 1-800-451-3115 x207 sales

International: 850-574-2369 x207 sales