

YOU NOW HAVE A CHOICE!

Introducing Superior's Newest 4R75 SuperTuff® Plate Giving You Two Superior Options!

Made in the U.S.A., both 4R75 SuperTuff® plates (K092 & K0192) are zinc coated and extra thick to stop flex and cracking. Both plates come with our famous "Snubber" to correct the wear on the nub of the 2-3 accumulator spring retainer. While they're the perfect replacement for a "stock" valve body plate (just match up your original 1-2 plate hole size) for correct use. If you prefer the Original K092 SuperTuff® Plate with the .092" 1-2 feed hole size, we find it works best with kits and upgrades and can be drilled larger to match "kit" instructions for feed hole size and accumulator spring choices.

Got a Smaller 1-2 feed orifice? That's where the "Choice" comes in.

With the NEW K0192 SuperTuff® plate, the new smaller .073" 1-2 feed hole works as a stock replacement on the later model 4R75's that came with a smaller 1-2 feed hole, and factory accumulator springs. It replaces stock plates found in most V-6/small V-8 units from 2008-current production. The good news is you can now keep your late accumulator spring set up if you just want to change the stock plate without firming the 1-2 shift. you can always use the K0192 as a start and if you want it firmed up, just drill the .073" 1-2 feed orifice to what ever size you want.

Remember, either plate can be modified when using your favorite Superior Shift Correction Package® or Fairbanks Performance® Product. Complete instructions on use and hole locations come with both SuperTuff® Plates.

PART# K092
.092" 1-2 feed hole

PART# K0192
.073" 1-2 feed hole

SUPERIOR
TRANSMISSION PARTS, INC.
THE SIMPLE SOLUTION®



VISIT OUR NEW INTERACTIVE WEBSITE:
www.superiortransmission.com

f Superior Transmission Parts, Inc. t superiortrans1

Phone: 1-800-451-3115 x207 sales

International: 850-574-2369 x207 sales